



Timing Relationship

B0504, B0508, B0512, 13BC, 16BHS, 16BHL, 22BHS, 22BHM, 22BHL




Timing relationships between the motor phases and the hall sensors that support commutation (four pole motor). CW rotation from shaft end.




Motor is supplied with connector AMP #640430-8 which may be removed.

B0610, B0614, B906, B909, B912, B1106, B1112, B1118, B1505, B1515, B1525, nuvoDisc series



Timing relationships between the motor phases and the hall sensors that support commutation (four pole motor). CW rotation from shaft end.



Motor is supplied with connector AMP #640430-8 which may be removed.